



Southeast Aerospace, Inc
1399 General Aviation Dr
Melbourne, Florida 32935 USA
sales@seaerospace.com
Tel: 321-255-9877
Fax: 321-255-9608
www.seaerospace.com

DHC-6 Twin Otter Capabilities List

| Part Number | Model | Description | Capability |
|--------------|------------|------------------|--------------------------|
| 060-0015-00 | KG-102A | Directional Gyro | Repair, Spares, Exchange |
| 066-1069-01 | KDI-572 | DME Indicator | Repair, Spares, Exchange |
| 066-3042-01 | KNI-581 | R.M.I. | Repair, Spares, Exchange |
| 066-3046-01 | KI-525A | H.S.I. | Repair, Spares, Exchange |
| 066-3046-07 | KI-525A | H.S.I. | Repair, Spares, Exchange |
| 071-1052-00 | KMT-112 | Flux Valve | Repair, Spares, Exchange |
| 071-1234-00 | KA-44B | ADF Antenna | Repair, Spares, Exchange |
| 101627-01696 | | Altimeter | Spares, Exchange |
| 101720-01455 | | Altimeter | Spares, Exchange |
| 102-0057-02 | RCA26BK-6 | Attitude Gyro | Spares, Exchange |
| 2587193-43 | C-14A | Directional Gyro | Repair, Spares, Exchange |
| 504-0010-903 | 500DCF | Attitude Gyro | Spares, Exchange |
| 504-0017-913 | 510-17A | Attitude Gyro | Repair, Spares, Exchange |
| 522-2638-006 | 331A-3G | H.S.I. | Repair, Spares, Exchange |
| 522-3082-001 | 331A-3F | H.S.I. | Repair, Spares, Exchange |
| 522-3306-00 | 331H-3G | Course Indicator | Repair, Spares, Exchange |
| 522-3306-000 | 331H-3G | Course Indicator | Repair, Spares, Exchange |
| 5934P-1A.56 | 5934P-1A56 | Altimeter | Repair, Spares, Exchange |
| 5934P-1A.83 | 5934P-1A83 | Altimeter | Repair, Spares, Exchange |
| 622-0555-003 | 332C-10 | R.M.I. | Repair, Spares, Exchange |
| 787-6385-002 | 331A-6P | Course Indicator | Repair, Spares, Exchange |
| 792-6694-001 | 332D-11A | Vertical Gyro | Repair, Spares, Exchange |
| KCA0104W | | Compass | Spares, Exchange |
| PC-15BC | | Inverter | Repair, Spares, Exchange |
| PC-250 | | Inverter | Repair, Spares, Exchange |
| RCA26BK-16 | | Attitude Gyro | Spares, Exchange |